


## SERVICE PROCEDURE: RC Extend-A-Gun Drive Box Replacement (for use with serial numbers above X505165)

The Extend-a-Gun Motor Drive Unit contains latches that hold the Extend-a-Gun in both the extended and retracted positions. The latches are fully automatic but rely on the Motor Drive Unit being synchronized to the gear rack on the Extend-a-Gun tube. **The Motor Drive Unit must be correctly timed whenever it is reinstalled or replaced.** This document shows how to obtain and verify the correct timing of the Motor Drive Unit.

- 1 Remove the monitor from the Extend-A-Gun.
- 2 Using a 3/16" long handled Allen wrench, remove the motor by removing the 2 motor mounting screws.
- 3 Remove the drive box by removing the 2 drive box mounting screws.





4 Ensure that the timing marks are in the correct orientation. This may take several knob rotations.

Knob shaft timing mark facing center of spur gear shaft.


Spur gear timing mark facing forward.



TASK FORCE TIPS, INC. MADE IN USA • www.tft.com 3701 Innovation Way, Valparaiso, IN 46383-9327 USA 800-348-2686 • 219-462-6161 • Fax 219-464-7155

- Fully extend the inner tube. One person will need to hold the tube in position while another person installs the new drive box.
- Install the drive box screws using blue Loctite thread locker. Alternate between the screws while tightening to ensure that the box stays flat against the mounting surface.





Verify that the tube latches in the fully extended and fully retracted positions and not in any intermittent positions. If intermittent latching occurs, remove the gearbox and check the orientation of the timing marks.



while in down position.



tube while turning knob.



To test down latch, pull up on tube To release down latch, push down on To test up latch, push down on tube while in up position.

- With the tube in the down position, attach the motor using blue Loctite thread locker on the screws.
- Cycle the Extend-A-Gun under power checking for proper operation up and down, and motor shutoff at stroke ends.